

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

C/SF
OP

Form C-103
Revised March 25, 1999

| | | |
|--|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-015-03361 |
| 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 2. Name of Operator Anadarko Petroleum Corp. | | 6. State Oil & Gas Lease No. |
| 3. Address of Operator P.O. Box 2497 Midland, TX 79702 | | 7. Lease Name or Unit Agreement Name: BALLARD GRAYBURG SAN ANDRES UNIT TRACT 22 |
| 4. Well Location Unit Letter <u>D</u> : <u>990</u> feet from the <u>NORTH</u> line and <u>330</u> feet from the <u>WEST</u> line Section <u>9</u> Township <u>18S</u> Range <u>29E</u> NMPM County <u>EDDY</u> | | 8. Well No. 4 |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) N/A | | 9. Pool name or Wildcat LOCO HILLS ON GB SA |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: CONVERT TO PRODUCER ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRUPU. KILL WELL. NDWH. NU & TEST BOPE. RLSE PKR & POOH W/TBG.
2. RIH W/PKR TO 2585'. ACIDIZE OPEN HOLE WITH 3000 GALS ACID. RLSE PKR & POOH.
3. RIH W/PKR & RBP. SET RBP @ 2585'. SET PKR @ 2500'. ACIDIZE PERFS W/2000 GALS ACID. RETRIEVE RBP & POOH.
4. RIH W/TBG. CIRC HOLE CLEAN. RIH W/PUMP & RODS.
5. INSTALL PUMPING UNIT. PLACE WELL ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE SABRA WOODY TITLE ENGR TECH III DATE 03/05/01

Type or print name SABRA WOODY Telephone No. 915/683-0534

(This space for State use)

APPROVED BY mrs S. Williford TITLE Field Rep. # DATE 3/14/01
Conditions of approval, if any:

Ballard GSAU #22-4

Loco Hills (Queen Grayburg San Andres) Injector
990' FNL & 330' FWL, Sec 9, T18S, R29E, Eddy Co., NM
Spudded 12/17/56

