

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ WIW-TA
2. NAME OF OPERATOR
Newmont Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 1305 Artesia, New Mexico 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input checked="" type="checkbox"/>
(other)			

5. LEASE
NM 02428
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
West Loco Hills GRB # 4 SD
8. FARM OR LEASE NAME
Tract 20
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Loco Hills (Q.G.SA)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
10-18s-29e
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3515'

RECEIVED
(NOTE: Submit results of multiple completion or zone change on Form 9-330.)
MAR 30 1983

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-28-83 100 sacks @ 2521'.
3-1-83 Tag @ 2520'. 75 sacks at 2510'.
3-2-83 Tag @ 2320'.
3-3-83 Perforate @ 835'. 50 sacks of cement @ 835'. (Squeeze)
3-4-83 55 sacks @ 835'.
3-7-83 Tag @ 670'. Perforate @ 335'. 50 sacks of cement @ 335'. (Squeeze)
3-8-83 55 sacks @ 335'.
3-9-83 Tag @ 182'. 15 sacks of cement for top plug. Set dry hole marker

Location ready for inspection

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Manager DATE 3/28/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 12/24/90
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

DEC 31 '90

O.
ARTESIA, N.M.