DEPARTI NT OF	F THE INILH	HUN verm Nov	المتمامة فعالم فيعامن المرابي المستدان والمستدان
GEOLOGICAL SURVEY			LC-058481
SUNDRY NOTICES AN  (Do not use this form for proposals to drill o  Use "APPLICATION FOR P	ID REPORTS	ON WHICEPIED	G. IP INDIAN, ALLOTTIC OR TRIBE NAME
1.		00111 12 00 11	7. UNIT AGREEMENT NAME West Loco Hills Grb #4 Se
WE'LL GAB WELL OTHER	WIW - TA	BUR OF LAND MGMT	8. FARM OR LEASE NAME
2. NAME OF OPERATOR	•	ROSWELL DISTRICT	Tract 11
Newmont 011 Company		RECEIVED BY	9. WELL NO.
		į	1
4. LOCATION OF WELL (Report location clearly and in See also space 17 below.) At surface	accordance with any	y State require 1941.28 1983	Loco Hills (Q.G.San)
•		O. C. D.	11. BEC., T., R., M., OR BLK. AND BURYET OR AREA
330' FNL 2310' FWL Sec. 11-18-29	9	ARTESIA, OFFICE	Sec. 11-18-29
	IONS (Show whether D	T PT CP AIR \	12. COUNTY OR PARISH   13. STATE
14. PERMIT NO. 15. ELEVATI	OS (Snow whether b	,, ki, un, easy	T 3 3
	_3251		Eddy
16. Check Appropriate E	3ox To Indicate I	Nature of Notice, Report, or	
NOTICE OF INTENTION TO:		. auss	EQUENT REPORT OF:
TEST WATER BRUT-OFF PULL OR ALTE	R CABING	WATER BHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COM	SPLETE	FRACTURE TREATMENT	ALTERING CABING
SHOOT OR ACIDIZE ABANDON*		P&A	ABANDONMENT*
REPAIR WELL CHANGE PLANS	•	(Other)(Norr: Report resu	lts of multiple completion on Well npletion Report and Log form.)
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clean	arly state all pertine	us desettly and also partinent dat	es including estimated date of starting and
17. DESCRIBE PROPUSED OF COMPLETED OPERATIONS (CIPS proposed work. If well is directionally drilled, nent to this work.) *	give subsurface loca	ations and measured and true veri	tical depths for all markers and sones perti
7/14/83Tagged bottom. Spotted 10 7/15/83Tagged plug at 1818'. Ho No pressure. WOC. Tagged WOC. 7/16/83 Tagged plug at 687'. Pre Spotted 50 sks cmt at 441 7/18/83Pressure up to 500 psi. Installed P&A Marker	ole between 9 ed plug at 87 essured up to 1' w/2% Calci	945 and 1039'. Squee 71'. Could not pressu o 500 psi @ 360'. Pe ium. Bullhead squeez	zed 50 sks cmt w/2% Calciumere up. Spotted 50 sks cmt  rf. w/4 shots at 400'.  ed w/800 psi. SI
Cleaned location, seeded	and ready fo	or inspectión.	
			Post 7 83 P+ P
18. I hereby certify the foregoing is tree and cor	TITLE	Area Manager	DATE9/14/83
(This space for Federal or State office pae)			
APPROVED BY	TITLE		DATE