

May 1983

C/SF

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

LC-060904

G. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA

OCT 11 12 51 AM '83

7. UNIT AGREEMENT NAME

West Loco Hills Grb #4 SI

2. NAME OF OPERATOR

BUR. OF LAND MGMT
ROSWELL DISTRICT

8. FARM OR LEASE NAME

Tract 13

3. ADDRESS OF OPERATOR
NEWMONT OIL COMPANY

9. WELL NO.

5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
P. O. Box 1305 Artesia, N.M. 88210

NOV 28 1983

10. FIELD AND POOL, OR WILDCAT

Loco Hills (O.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 12, T18S, R29E NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3526' Gr.

12. COUNTY OR PARISH

Eddy

13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) P&A

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7/25/83....Tagged bottom and pulled up 1 jt. Spotted 100 sks cement w/2% Calcium.

7/26/83....Tagged plug at 2307'. Pressure tested csg 500 psi. Held. Perf. w/4 shots at 1130 Ran packer to 819' and set. Squeezed 50 sks. cement. SI w/500 psi. WOC. Tagged plug at 975'. Mixed 15 sks cmt - pushed into channels of plug. SI overnight.

7/27/83....Pressured to 500 psi. Held. Tagged plug at 960'. Perf 330' w/4 shots. Squeeze 50 sks cmt w/2% Calcium. WOC. Pressured to 500 psi. Tagged plug at 219'. Mixed 15 sks cmt w/2% Calcium. Installed P&A Marker.

Location cleaned, seeded and ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE 9/14/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post ID-2
12-2-83
P&A