

Flaw 350 BPD = Called for Jerry Not in left word,
talked to Lee

ID 2904 P BW/ rock + lead wool
to 2640 set 5 1/2" 2640-1005X, log-2689
test OH- 2640-89 set DP @ 2620 + F 2528-36
F 2539-45-

8" hole = 5.4 LFPCF surface csg. set @ 360 cut + pulled from 167

100
5.4
400
5000
5400
✓ 11000 28000
F = 1800 Circ Cement to surface - back flow
up csg until cement sets then sq.

Flaw - 6-19-

100 BPD =

BP ann 35'

spot 25-

Pat. -

WOC. 12

Salt. 10-12"

monday - wed. -

Comp.