

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42 R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.
(Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

SEP 22 1980

O. C. D.
ARTESIA, OFFICE1. ☒ AS WELL ☐ OTHER

2. NAME OF OPERATOR

Anadarko Production Company

3. ADDRESS OF OPERATOR

P. O. Box 67, Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See space below.

1650' FNL & 990' FWL Sec. 17, T18S, R29E
Eddy County, New Mexico

14. LOCATION

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3515' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM - 14843

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Ballard Grayburg
San Andres Unit

8. FARM OR LEASE NAME

Tract No. 20

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Loco Hills-Queen-
Grayburg San Andres11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

17 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

YES WATER SHUT-OFF

PULL OR ALTER CASING

FRACURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

Temp. Re-activate T. A. well

XX

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

16. DETAILS OF PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Rigged up pulling unit.
2. Ran 570' (19 joints) 5½", 20#, 10V casing. Screwed into collar on existing 5½" casing. Pulled tension and hung on slips.
3. Drilled bridge @ 1306'.
4. Drilled bridge @ 2415'.
5. Cleaned out with bit to 2505'; drilled on junk iron.
6. Ran 6" washpipe and washed over junk tubing from 2505' to 2580'.
7. Lost 6" washpipe in hole. Top @ 2401' - bottom @ 2580'.
8. Could not fish washpipe.
9. Cleaned out with bit down beside 6" washpipe to 2491'.
10. Ran tubing, rods & bottom-hole pump.
11. Set temporary production equipment and test-pumped. The well produced only water &/or mud and has been returned to T. A. status.

Note: "Application for Permit to Drill" a replacement well (Ballard #20-12) has been approved. Plan to file to P & A this well once #20-12 has been drilled and POP.

ACCEPTED FOR RECORD

SEP 18 1980

17. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supervisor

U.S. GEOLOGICAL SURVEY
DATE Sept 16, 1980
ROSWEIL, NEW MEXICO

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: