

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM - 54183

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Travis 'D' Federal

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Loco Hills-Queen-Grayburg-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

18 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Anadarko Production Company

3. ADDRESS OF OPERATOR

P. O. Drawer 130, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below)  
At surface

660' FS & ELs

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3563' DF

### 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Re-complete

X

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. RUPU; TOH with rods and tubing.
2. Rig up wireline; dump 35' cement on CIBP @ 2880' to plug off San Andres Formation. Set CIBP @ 2625' and dump 35' cement on CIBP to shut off Premier perms of Grayburg Zone. Set CIBP @ 2515' to shut off Metex perms of Grayburg Zone. Perforate Loco Hills Zone of Grayburg from 2420' to 2430'.
3. GIH with packer and tubing.
4. Acidize and fracture treat Loco Hills Zone.
5. TOH with packer.
6. Run tubing, rods and bottomhole pump.
7. Place well on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED Mike Brewwell

TITLE Field Foreman

DATE January 10, 1985

(This space for Federal or State office use)

APPROVED BY Don Wood

TITLE AREA MANAGER

DATE 1-17-85

CONDITIONS OF APPROVAL, IF ANY

\*See Instructions on Reverse Side