	D. UJENISSION
RECEI' ) BY Drawer DD	95
Artesia, N	
Form 9-331 Dec. 1973 SEP 3 0 1983	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC 063808
GETLLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Ballard Grayburg San Andres Unit
(Do not use this form for proposals to drill or to deepen or plug back to a differen reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Tract No. 16-A
1. oil gas well well other	9. WELL NO.
2. NAME OF OPERATOR	1
Anadarko Production Company	10. FIELD OR WILDCAT NAME Loco Hills-Queen-Grayburg-San Andres
3. ADDRESS OF OPERATOR P. O. Drawer 130, Artesia, New Mexico 88210	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
below.)	18 - 18S - 29E
AT SURFACE: 330' FN & ELS Sec. 18, T18S, R29E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: <b>Same</b> AT TOTAL DEPTH: Same	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	3555'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
	NB GGS V (2
REPAIR WELL	(NOTE: Report require of multiple completion or 2014) change on Form 9–330.)
	OCT 2 9 1982
CHANGE ZONES	
ABANDON*	OIL & GAS
	MINERALS MGMT. SERVICE
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, USAN Elve NEW in MEXICO tes, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertinent to this work.)*	
1. Rigged up pulling unit; tripped out of hole with rods and tubing.	
<ol> <li>Ran Lynes Open Hole packer and set @ 2380'.</li> <li>Halliburton fraced with20,000 gals X-link gel, 16,000# 100 Mesh sand &amp; 28,000#</li> </ol>	
3. Halliburton fraced with20,000 gals X-link gel, 16,000# 100 Mesh sand 28,000# 20/40 sand; open hole packer failed; tripped out of hole with packer.	
3. Ran 7" RTTS packer and set @ 2188'.	
4. Halliburton fraced with 30,000 gals X-link gel, 20,000# 100 mesh sand, 42,000#	
20/40 sand, 14,000# 10/20 sand & 1 drum corrosion inhibitor; casing packer	
failed. 5. Rigged up reverse unit and cleaned out fill to 2700'; re-ran 7" RTTS packer	
5. Rigged up reverse unit and cleaned out fill to 2/00; re-ran / Kills packer and set @ 2175. in 4 stages	
6. Halliburton fraced with 77,000 gals X-link gel, 32,000# 100 M sand, 87,000#	
20/40 sand, 30,000# 10/20 sand and 1 drum corrosion inhibitor + 2 drums scale	
inhibitor, $ARAP = 21.5 BPM @ 2600\%$ .	
7. Pulled 7" pkr. washed out frac sand; re-ran tubing & rods & returned to pump. Subsurface Safety Valve: Manu. and Type Ft.	
18. I hereby certify that the foregoing is true and correct	
signer Area Supervisor DATE October 28, 1982	
SIGNED DATE DATE	
ACCEPTED FOR RECOTHs space for Federal or State office use)	
APPROVED BY PETER W. CHESTER TITLE DATE	
CONDITIONS OF A PROVAL IF ANY:	
SEP 29 1983	
₹.) <b>•</b> . A	
*See Instructions on Reverse Side	

.

ŧ