

UNITED STATES M. O. C. DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-067132

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR **KERSEY & COMPANY & E. A. HANSON** **FEB 5 1975**

3. ADDRESS OF OPERATOR **P. O. Box 316, Artesia, New Mexico 88210**

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.)
At surface **330' N of S line - 1650' W of E line**
Section 21, T10S, R29E, N12PM
330/S 1650/E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3463 Ground Level

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Denton

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Turkey Track

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
21-18-29

12. COUNTY OR PARISH
Eddy

13. STATE
N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Program followed plugging Denton #2

1. Put 100' cement plug across perforations at 1991 - 1998'
2. Filled hole with heavy mud.
3. Put 100' cement plug across 814' where 4 1/2" casing shot off.
4. Put 100' cement plug in and out of 8 5/8" casing shoe at 356'
5. 20' cement plug at the surface with markers.

RECEIVED
JAN 27 1975
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE

Owner

DATE

1/24/75

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side