			ANS COMMINE O/C	
orm 3160-5	UN	D STATES	NM OIL CONS COMMIS- DD FORM APPROVED C/S	
lune 1990)	DEPARTMENT	OF THE INTERIOR		
	BUREAU OF LA	ND MANAGEMENT	ATUS: Lease Designation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS			6. If Indian, Allottee or Tribe Name	
		or to deepen or reentry to a difference "ERMIT—" for such proposals		
	7. If Unit or CA, Agreement Designation			
Type of Well	· · · · · · · · · · · · · · · · · · ·			
Vell Gas (	8. Well Name and No.			
2. Name of Operator			Brainard Tract 4 #6	
Mack Energy Address and Telephone No.			9. API Well No.	
P.O. Box 1359 - Artesia, New Mexico 88211-1359			10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area	
			11. County or Parish, State	
Sec. 34 T-18-S R	2-29-E 2204 FS	EL 2310 FEL	Eddy, N.M.	
CHECK APPR	OPRIATE BOX(s) T	O INDICATE NATURE OF NOTI		
TYPE OF SUBMI				
Notice of Intent				
- Nonce of Intent			Change of Plans  New Construction	
Subsequent Report	τ			
_		Casing Repair		
Final Abandonmen	nt Notice	Altering Casing	Conversion D Injection	
		Other	Dispose Water 23	
			(Note: Report rEfulls of multiple completion on Well Completion or Recompletion Report and Log form )	
give subsurface locations and a	measured and true vertical dept	ent details, and give pertinent dates, including estimate hs for all markers and zones pertinent to this work.)	ed date of starting any proposed work. If well is directionally drilled,	
1) Circ hole W/m	ud laden fluid			
	lug of CIBP set	ə 1995		
3) Perf csg 50' below base salt (985')			ERS 195	
1) Squeeze perf (				
5) Tag plug @ 88		2/41		
6) Perf csg 50' 1 7) Squeeze perf l	below top salt (	364 )		
8) Tag plug @ 26				
9) Perf csg @ 60		REC	EWED	
	W/cmt. Attempt t	to Circ cmt to surface on a		
			I have a	
	ole marker and c	lean Location		
		this location APR	1 1 1995	
	ole marker and c	this location APR	1 1 1995	
	ole marker and c	this location APR	1 1 1995 NNI 10111 (	
	ole marker and c	this location APR	1 1 1995 NNI 1011 4	
	ole marker and c	this location APR	1 1 1995 NNI 10 10 4	
2) We will need (	ole marker and c workover pit on	this location APR	1 1 1995 NNI 1011 4	
12) We will need (	ole marker and c workover pit on	this location APR	1 1 1995 NNI 1011 4	
hereby certify that the foregoing is	ole marker and c workover pit on strue and correct / aldwinate	this location APR	1 1 1995 NNI 10 10 4	
hereby certify that the foregoing is igned <u>Hereby many</u>	ole marker and c workover pit on strue and correct ) (L) (dw mark) ice use)	this location APR OIL CO DIS Title Lupers 1000	1 1 1995 DIN. DIV. T. 2 Date <u>14 - 14 - 9 S</u>	
2) We will need a hereby certify that the foregoing is gned <u>Alexander</u> his space for Federal or State office pproved by <u>Oder Signad</u>	ole marker and c workover pit on strue and correct / aldwinate	this location APR OIL CO DIS	1 1 1995 DIN. DIV. T. 2 Date <u>14 - 14 - 9 S</u>	
2) We will need a hereby certify that the foregoing is gned <u>Hill Man</u>	ole marker and c workover pit on strue and correct <u>Illala national</u> ice use) y idam Salameh	this location APR OIL CO DIS Title Lupers 1000	1 1 1995 DIV. DIV. T. 2 	

le 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements representations as to any matter within its jurisdiction.

# MACK ENERGY CORPORATION

## BRAINARD 4 #6 SEC 34 T18S R29E 2204FSL 2310FEL

### WELL HISTORY

- SHOWS: 975-85,1495-1510
- **PBTD:** 2110'
- TD: 2110'
- SP Csg: 8 5/8" 24# @ 329' C/w 20sx
- LS Csg: 5 1/2" 15# @ 2099' C/w 30sx
- T SALT: 314'
- B SALT: 935'
- PERFS: Open hole 2099-2110

#### COMPLETION REPORT

12-12-58 Frac open hole w/19000 gals and 285sx Sand.

#### WELL REPORT

5-5-94 Ran in hole w/CIBP and Set @ 1995'. Tested Csg to 300# Held OK.

## 3-30-95 PROPOSE TO PLUG AND ABANDON AS FOLLOWS:

- 1 Circ hole w/mud laden fluid
- 2 Set 2sx Cmt plug of CIBP set @ 1995
- 3 Perf csg 50' below base salt (985')
- 4 Squeeze perf w/25sx Cmt
- 5 Tag plug @ 885'
- 6 Perf csg 50' below top sait (364')
- 7 Squeeze perf w/25sx Cmt
- 8 Tag plug @ 265'
- 9 Perf csg @ 60'
- 10 Squeeze perf w/cmt, Attempt to Circ cmt to surface on all csg.
- 11 Install dry hole marker and clean location.
- 12 We will need workover pit on this location





(Rev. 5/23/94)

.

#### BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Permanent Abandonment of Wells on Federal Lands

#### Conditions of Approval

1. <u>Approval:</u> Plugging operations shall commence within 98 days from the approval date of plugging procedure.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544; for wells in Lea County call (505) 393-3612.

3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks ( 56 pounds each ) of gel per 166 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirements</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 18-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.