

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL & GAS
Artesia, NM 88210

Form approved
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.
NM 021095
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WIW - TA		7. UNIT AGREEMENT NAME LOCO HILLS FLOOD	
2. NAME OF OPERATOR NEWMONT OIL COMPANY		8. FARM OR LEASE NAME YATES "A"	
3. ADDRESS OF OPERATOR P. O. BOX 1305 ARTESIA, NEW MEXICO 88210		9. WELL NO. 11	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL 1650' FEL Sec. 6-18-30		10. FIELD AND POOL, OR WILDCAT LOCO HILLS (Q. G. SA)	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6-18-30	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3546'		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

RECEIVED

SEP 1 1982

O. C. D.

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Pull tubing and packer
2. Spot sufficient cement across producing interval to tie back to production string casing seat, or set bridge plug near casing seat and cap with 25 sack cement plug.
3. Perforate base of salt @ 1122' and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate top of salt @ 420' and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface tying surface and production casing together.
6. Erect permanent well marker

Note: (A.) Your office will be notified 24 hrs. prior to operations.
(B.) All plugs will be verified
(C.) Hole will be loaded between all plugs with 10# mud
(D.) We do not plan to pull any casing.

RECEIVED
JUL 30 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED <i>Peter W. Chester</i>	TITLE Area Manager	DATE 7/28/82
(This space for Federal or State Seal Use)		
APPROVED BY (Orig. Sgd.) PETER W. CHESTER	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY: AUG 31 1982		
FOR JAMES A. GILLHAM* See Instructions on Reverse Side DISTRICT SUPERVISOR		