



UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL & GAS

MISSION

Form approved.  
Budget Bureau No. 42-R1424.

45F

SUNDRY NOTICES AND REPORTS ON WELLS

Do Not Use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ARTESIA, OFFICE

OIL WELL ☐ GAS WELL ☐ OTHER

WIW - ~~W~~ P & A

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

Yates Pet. Corp.

3. ADDRESS OF OPERATOR

P. O. BOX 1305---ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

990' FNL 1650' FEL Sec. 6-18-30

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.

NM 021095

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Loco Hills Flood

8. FARM OR LEASE NAME

Yates "A"

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 6-18-30

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well was plugged and abandon as follows.....

11/2/82.....Spotted 50 sack cement plug at approx. 2800'. Shut down

11/3/82.,...Tagged plug at approx. 2458'. Hole in casing. Started looking for hole, leaking at 1493', 1368' @ 1243'. Pump in formation, set packer @ 1053' and squeezed hole with 50 sacks cement. Shut down

11/4/82.....Tagged plug at 1236'. Pressured up on casing to 800 psi, okay. Perf base of salt @ 1122' and squeezed with 50 sacks cement.

11/5/82.....Tagged @ 930'. Pressured up to 800 psi. Okay. Perf top of salt @ 420'. Squeezed w/110 sacks cement. S.D.

11/6/82.....Tagged plug at 310', pressured up to 800#. Okay. Set 15 sack cement plug and dry hole marker on surface.

Location ready for inspection.

RECEIVED

MAR 23 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

*Ernest J. McLaughlin*

TITLE

Area Manager

OIL & GAS

MINERALS MGMT. SERVICE

ROSWELL, NEW MEXICO

3/22/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

9-23-83