

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 021095

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

LOCO HILLS FLOOD

8. FARM OR LEASE NAME

YATES "A"

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

LOCO HILLS (O.G.S.A.)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 6-18-30

12. COUNTY OR PARISH

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305 ----- ARTESIA, N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL 1310' FEL Sec. 6/18/30

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3555'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandoned as follows:

10/20/82....Spotted 50 sack cement plug at 2793'. Tagged plugs at 2333'. Mudded up and perf bottom of salt at 1142' and squeezed w/50 sacks cement.

10/21/82....Tagged plug 2333'. Moved packer up until no more circ. Set packer @ 600' and squeezed 200 sacks cement.

10/22/82....Tagged plug at 740'. Pressure tested to 800 psi, perf. @ 441' and squeezed 160 sacks cement.

10/23/82....Tagged plug at 315'. Set 15 sack surface plug and dry hole marker.

Location ready for inspection.

RECEIVED

MAR 23 1983

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE

3/22/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

10 24 84

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post FD-2
4-1-83
PKA