	Theory Constraints	Form approved.
DEFARTMENT OF THE INTER OT	(Uther Instru A on re-	Hudget Bureau No. 42-R1424. LEAKE DERIGNATION AND BERIAL NO.
		NM-025623
SFP 23 1903		IF INDIAN, ALLOTTEE OR THIRE NAME
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back to ARTESIA, OFFICE Use "APPLICATION FOR PERMIT_" for such proposals OCT I	A GMERKED Servoir.	
ARTESIA, OFFICE Use "APPLICATION FOR PERMIT_ IN DET	12 34 44 192 7.	UNIT AGREEMENT NAME
WELL OTHER WIW TA		EST LOCO HILLS GRB #4 SD
2. NAME OF OPERATOR ROSW	ELL DISTRICT	FARM OR LEASE NAME UT Tract 22
NEWMONI OIL COMPANY		WELL NO.
3. ADDRESS OF OPERATOR P. O. BOX 1305, ARTESIA, NEW MEXICO	88210	1
 LOCATION OF WELL (Report location clearly and in accordance with any State r See also space 17 below.) 	equirements. • 10). FIELD AND POOL, OR WILDCAT LOCO HI11s (Q.G.SA)
At surface	11	L. BEC., T., R., M., OR BLK. AND BURVEY OR AREA
660' FSL 1980' FWL Sec. 7-18-30		Sec. 7-18-30
14 DEBAULT NO. 15. ELEVATIONS (Show whether DF, RT, GR,	etc.)	2. COUNTY OR PARISH 13. STATE
14. (David no.		Eddy N.M
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO:	WATER SHUT-OFF	REPAIRING WELL
TEST WATER BHUT-OFF PULL OR ALTER CASING	FRACTURE TREATMENT	ALTERING CABING
BJIOOT OR ACIDIZE ABANDON*	BHOOTING OR ACIDIZING	ABANDONMENT [®]
REPAIR WELL CHANGE PLANS	(Other) (Norg: Report results of Completion or Recompletion	nultiple completion on Well n Report and Log form.)
17. DESCRIPT. PROPOSED OR CONFLETED OFERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-		
Nent to this work.)* 8/8/83Ran in hole with packer to 2400'. Pump rate 2 bb1/min at 400 psi. Squeezed		
8/8/83Ran in hole with packer to 2400 . "Tump fully 2 bot, min at not point of packer to 2400 . bottomhole plug with 50 sks Class "C" cement with 2% Calcium. Shut in with 400		
psi.		
8/9/83Pressure tested bottomhole plug to 500 psi. Ran wireline in hole to tag plug,		
wouldn't go through packer. Came out of hole with wireline. Checked for hole		
in csg. Csg good. Ran wireline and tagged plug at 2550'. Pulled up to 1180'		
and perf. Pump rate 2 bbl/min 800 psi. Land packer at 819' and squeezed 50 sks Class "C" cement with 2% Calcium. Shut in pressure 600 psi. WOC.4 hrs.		
Pressure test plug at 500 psi, good. Laid down tbg and ran wireline to tag plug		
Plug at 1040'. Pulled up to 400' and perf. Circ. to pit. Land packer at 63'		
and squeezed 50 sks Class "C" with 2% Calcium. Shut in - no pressure.		
8/10/83Pressure up on plug to 500 psi. Un to tag plug. Plug at 300'. Mixed Marker.	set packer and laid 15 sks top hole plug	down tbg. Ran tbg in g and installed P&A
		•
Location cleaned, seeded and ready	for inspection.	
		• 7
		·
18. I hereby certify that the porepoing is true and correct		0/1//00
SIGNED Finest fille prage TITLE Are	a Manager	DATE9/14/83
(This space for Federal for State affice unit		6-7205
APPROVED BY TITLE		DATE 9-23-85
CONDITIONS OF APPROVAL, IF ANY:		

ţ

*See Instructions on Reverse Side