

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN _____ INDICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028728 a 024978(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TEXACO Inc. ✓		8. FARM OR LEASE NAME L.R. Manning Fed. "a"
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 330' from the North Line, and 1650' from the East Line of Section 21, T-18-S, R-30-E, Eddy County, N.M.		10. FIELD AND POOL, OR WILDCAT Lec
14. PERMIT NO. Regular		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T-18-S, R-30-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3463' (D. F.)		12. COUNTY OR PARISH Eddy
		13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Subject well has been plugged and abandoned as follows:

1. Pull pump equipment.
2. Spot 100 Sx. cement from 2950' to 3133'.
3. Shot off 7" O. D. Casing at 1100', recovered same.
4. Spot 40 Sx. cement from 1050' to 1150'.
5. Spot 50 Sx. cement from 475' to 575'.
6. Spot 20 Sx. cement surface plug 0' to 50'.
7. Clean location for inspection as per the United States Department of The Interior Geological Survey regulations, install 4" marker extending 4' above ground level. Plug and abandon complete 8:00 A. M. January 19, 1966.

RECEIVED
JAN 25 1966
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett

TITLE Assistant District

DATE January 24, 1966

(This space for Federal or State office use)

Superintendent

APPROVED BY
COMPLETION OF APPROVAL IF ANY:

TITLE

DATE

APPROVED
JAN 3 1966

R. L. BEEKMAN
DISTRICT ENGINEER

*See Instructions on Reverse Side