			COSF						
Form 9-331	IJ	TED STATE	Form approv						
(May 1963)	-			JATE• on re-	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.				
DEPARTMLINT OF THE INTERIOR (Other Instruction, on re- GEOLOGICAL SURVEY						LC-028990-a			
	6. IF INDIAN, ALLOTTE	E.OR TRIBE NAME							
SUN		RECEIVED							
(Do not use this i	orm for proposal Use "APPLICAT!	s to drill or to deepe ION FOR PERMIT—"	n or plug back to for shell proposi	o a different reservoir					
1.	·····	<u> </u>				7. UNIT AGREEMENT	AIE 9 1980		
OIL X GAS (OTHER						0 1000		
2. NAME OF OPERATOR			APR	2 1980		8. FARM OR LEASE	^{IE} C, D.		
	l Oil Corpo	ration		• • •		Creek ARTE	SIA. OFFICE		
3. ADDRESS OF OPERATOR				UGICAL SURVEY		9. WELL NO.	,		
P. O. Box	· · - · · · · · · · · · · · · · · · · ·	#1							
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 						10. FIELD AND POOL, OR WILDCAT Leo Q-L			
330' FNL and 1650' FWL of Section 23.						11. SEC., T., B., M., OR BLK. AND			
JJO FNL		SURVEY OR AREA	· · · · · · · · · · · · · · · · · · ·						
		Sec. 23, T-18-S, R-30-E							
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)						12. COUNTY OR PARISE	1 13. STATE		
3456' DF						Eddy	New Mexico		
16.	Check App	ropriate Box To Ir	ndicate Natur	e of Notice, Repo	rt, or O	ther Data			
						JENT REPORT OF:			
		LL OR ALTER CASING							
TEST WATER SHUT-OF FRACTURE TREAT	<u> </u>	LL OR ALTER CASING		WATER SHUT-OFF FRACTURE TREATMEN	x X	REPAIRING ALTERING C			
SHOOT OR ACIDIZE		ANDON*		SHOUTING OR ACIDIZ		ABANDONME			
REPAIR WELL		ANGE PLANS		(Other)					
(Other)	·			(NOTE : Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					
17. DES RIBE PROPOSED OR	COMPLETED OPERA	TIONS (Clearly state ;	ul pertinent deta	ils, and give pertinen	nt dates,	including estimated dat	te of starting any		
nent to this work. 11	wen is directiona	ny urineu, give subs	uriace locations (ina mensurea nua tra	e vertical	depths for all marker	s and zones perti-		
					7				
		0	0	na and cleane ma Ray Neutro		well to T.D.	WITU		
reverse t	mit. ruii	eu cubing an	u tall a Ga	ha hay neutro	on rog	•			
Ban frac	tubing and	set RTTS Da	cker at 31	59'. Spotted	1 1 5%	HCL acid and a	sand		
fraced wi	th 16.000#	20/40 sand	and 21,000	# 10/20 sand	from	3240-80' (0.	н.).		
	• •	,		, ,		-	,		
Pulled pa	.cker and f	rac tubing.	Ran tubin	g and rods ar	nd put	well on prod	uction.		

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE	Secretary	DATE	March	31,	1980
(This space for Federal or State office use)				APh		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE _			

.