CISM		D. COPY	N.M. O.				
No. 42-R1424.	Form approved. Budget Bureau No 5. LEASE DESIGNATION AND	IOR SUBMIT IN TR' CATE. (Other instructic on re- verse side) 5.	U FED STATES PARTMENT OF THE INT	May 1963)	Form 9-331 (May 1963)		
CEIVED	LC-028990A	1	GEOLOGICAL SURVEY				
2.5 1980	6. IF INDIAN, ALLOTTER OF	ON WELLS	NOTICES AND REPORT for proposals to drill or to deepen or p "APPLICATION FOR PERMIT-" for a				
	7. UNIT AGREEMENT NAME	7.			<u>1.</u>		
C D.	0 (FED 01 4000	OTHER	WE'L GAB GAB			
SEA, OFFI CE	B. FARM OR LEASE NAME Creek		. /	. NAME OF OPERATOR Kersey & Company			
	9. WELL NO.	- BLULUGICAL SURVEY		ADDRESS OF OPERATOS			
	#2-🏎	RTESIA, NEW MEXICU	P. O. Box 548, Artesia, New Mexico 88210ARTESIA, NEW MEXICO				
WILDCAT	10. FIELD AND POOL, OR WIL		location clearly and in accordance with	, LOCATION OF WELL (Report lo	4. LOCATION OF		
Leo				See also space 17 below.) At surface			
K. AND	11. SPC., T., R., M., OR BLK. A SURVEY OR AREA	11	1650' FNL and 1665' FWL				
-S, R-30-E	Sec. 23, T-18-S,	5					
18. STATE	12. COUNTY OR PARISH 18.	F, RT, GR, etc.) 12	15. BLEVATIONS (Show wheth	4. PERMIT NO.	14. PERMI		
New Mexico	Eddy New						
	ther Data	Nature of Notice, Report, or Othe	heck Appropriate Box To Indica	8. Ch	16.		
	ENT REPORT OF:	SUBSDQUENT	NOTICE OF INTENTION TO :				
	REPAIRING WELL	WATER SHUT-OFF	PULL OB ALTER CASING	TEST WATER SHUT-OFF			
ING	ALTERING CASING	FRACTURE TREATMENT	MULTIPLE COMPLETE	FRACTURE TREAT			
•	ABANDONMENT*	SHOOTING OR ACIDIZING	ABANDON*	SHOOT OR ACIDIZE			
	·	(Other)	CHANGE PLANS	REPAIR WELL			
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				(Other)			
a Well	REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on W tion Report and Log form.) including estimated date of t	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of 1	PULL OB ALTER CASING	TEST WATER BHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Uther) 7. DESCRIBE PROPOSED OR COMPLI-			

Clean out to T.D.

Run Gama Ray Neutron and Cement Bond Logs.

Set packer at 3100 and frac thru tubing from 3228-3279 (0.H.) with 43500# 20/40 sand and 9,000# 10/20 sand.

Put well back on production.

18. I hereby certify that the foregoing is true and correct SIGNED Learge Long	Agent TITLE Arrowhead Oil Corp.	DATE 2/19/80
(This space for Federal or State office use)		FED OD IT
APPROVED BY <u>Sgd.</u> GEORGE H. STEWALL CONDITIONS OF APPROVAL, IF ANY:	TITLE TO BE THE ENONCEP	PEB 2 ≥ 198(, _ DATE