

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-028978-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO INC.

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface 1980' FNL & 660' FEL of Section 33,
T-18-S, R-30-E, Unit Letter 'H', Eddy County,
New Mexico

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NA

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

McClay Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

N. Benson Queen Grayburg

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA
Sec. 33, T-18-S,
R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Install BOP.
2. Set cement retainer @ 2844'. Dumped 60 sx. cement on retainer.
3. Perforated 5 1/2" csg. @ 1530'. Set pkr. @ 1302'. Squeeze w/125 sx. Class H cement. WOC.
4. Test w/900# for 30 minutes. Tested O.K.
5. Perforated @ 530'. Squeeze perforations w/125 sx. cement.
6. Set 43' (5 sx.) cement plug @ surface.
7. Install dry hole marker. Clean up. Well P & A 12-20-76.

RECEIVED

DEC 27 1976

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE 12-22-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 28 1977

H. L. CLEGG
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side