Form 3160-5 (November 1983) (Formerly 9-331) UNITE STATES DEPARTMENT of THE INT	NM OIL CONS COMMIS OTHER PLANT TO THE TENT OF THE TEN	5. LEASE DESIGNATION AND BI	
SUNDRY NOTICES AND REPOR (Do not use this form for proposals to drill or to deepen or use "APPLICATION FOR PERMIT—" for	plug back to a different reservois	NMNM 27276 6. IF INDIAN, ALLOTTEE OR TE	HE NAME
OIL X GAS OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR C.E. LARUE		8. FARM OR LEASE NAME MC CLAY	
3. ADDRESS OF OPERATOR		9. WELL NO.	
PO BOX 470 ARTESIA, NM 88211-0470		3	
 LOCATION OF WELL (Report location clearly and in accordance with See also space 17 below.) At surface 	h any State requirements.	10. FIELD AND POOL, OR WILL	CAT
1980' FSL AND 1980' FEL SECTION 33, T18S, R30E	SEP 27.'94	N. BENSON QUEEN 11. SEC., T., B., M., OR BLK. AN SURVEY OR ARMA	ro
	O. C. D	SEC. 33, T18S,	R30E
API # 30-015-04559 3415 GL	ther DF, RT, CR, etc.) ARTESIA, OFFICE	12. COUNTY OR PARISH 13. EDDY	NM NM
16. Check Appropriate Box To India	ate Nature of Notice, Report, or C	other Data	
NOTICE OF INTENTION TO:	. SUBSEQU	ENT EMPORT OF:	•
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING WELL	X
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE ABANDON* REPAIR WELL CHANGE PLANS	SHOOTING OR ACIDIZING	ABANDON MENT*	
(Other)	(Other) (Nors: Report results	of multiple completion on W	ell
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all p proposed work. If well is directionally drilled, give subsurfament to this work.)	artinung dataile and the most and the	etion Report and Log form.) Including estimated date of s il depths for all markers and	starting any zones perti-
7-28-94 OPENED WELL. RAN NEW PUMP & RODS REPACKED STUFFING BOX. RIGGED DOWN AND C	LEANED LOCATION. DUP FOR TUBING. DROPPED S	ING ON. GOOD PUMP	ACTION. JLLED TO ED 4 JOINT
ABOVE FLUID LEVEL. RAN TUBING BACK IN. 'LAND TUBING. RIGGED UP FOR RODS. RAN PUPUMP ACTION. LEFT WELL ON DOWN STROKE.	TAGGED FILL WITH 100 JOINTS MP & RODS IN. RESPACED WEI	LAID DOWN 1 JO	INT. GOOD
FORF ACTION. BEFT WELL ON DOWN STROKE.	shot bour.		
7-30-94 LEFT WELL DOWN TO LET "TRASH" SE	TTLE OUT OF FLUID.	ተ ፍ ን ያች	•
		K.	: :11
8-1-94 PUT WELL BACK ON PRODUCTION.		ware or ware to a	1 1 1
	I Lira	عسر ا	a *[],
	L. Jara 23 1994	lai Lai	171 (1)
	20	· · · · · · · · · · · · · · · · · · ·	
		. See See See See See See See See See Se	
18. I hereby certify that the foregoing is true and correct SIGNED MOLLY SMILLS TITL	E LEASE RECORDS	DATE 8-24-94	
(This space for Federal or State office use)			
APPROVED BY TITL CONDITIONS OF APPROVAL, IF ANY:	Σ	DATE	