

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Belly Unit
2. NAME OF OPERATOR Belly Oil Company	8. FARM OR LEASE NAME Belly Unit
3. ADDRESS OF OPERATOR P. O. Box 730, Santa Fe, New Mexico 87500	9. WELL NO. 21
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1000' N. 1000' E. Sec. 24-17-31	10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24-17-31
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3724	12. COUNTY OR PARISH Sandoval
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well is presently from open hole section 3080' - 3720' in the San Andres Formation. We propose to perforate and treat as follows:

1. Move in and run up pulling unit.
2. Pull rods, lower tubing to check for fillup, pull tubing.
3. Run collar log, perforate 5-1/2" casing from 3320' - 3574' for a total of 14 shots.
4. Run tubing with bridge plug and packer. Set plug between 3000' and 3080'. Raise packer above 3100'.
5. Acidize 3000' - 3574' with 1000 gallons and ball sealers.
6. Pull tubing and packer.
7. Fracture zone casing with 10,000 gallons sand-water.
8. Run tubing and retrieve bridge plug.
9. Run tubing and rods and return well to a producing status.

Intent was filed and permission was received to perforate and treat on November 20, 1967, but work was not performed.

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) L. E. Fletcher TITLE District Production Ex. DATE June 4, 1967

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
JUN-5 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED
JUN 4 1969

U. S. GEOLOGICAL SURVEY

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.