

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMXO-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection		3a. Area Code & Phone No. 505-672-2266	
2. NAME OF OPERATOR William A. & Edward R. Hudson ✓		8. FARM OR LEASE NAME Puckett "A"	
3. ADDRESS OF OPERATOR Box 9, Maljamar, New Mexico 88264		9. WELL NO. 21	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1295' from the north line, 2545' from east line, Sec. 24-T17S-31E W. B		10. FIELD AND POOL, OR WILDCAT Maljamar G-SA	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24-T17S-31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3903 DF		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

March 6, 1990, this injection well was permanently plugged and abandoned using the following procedure;

Set a "cast iron" bridge plug in 5-1/2" casing at 3370', loaded hole w/salt gel mud, spotted 50' cement on top of the plug, spotted 100' cement from 1810' to 1710', perforated 5-1/2" csg. at 640' w/4 holes, set a packer at 500', circulated fluid to surface, pulled packer, installed a 5-1/2" swage in top of csg., pumped cement down csg. and circulated cement to the surface. This procedure was witnessed and approved by BLM representative Jim Amos. Shut well in overnight, March 7, 1990, installed dry hole marker w/all well data.

March 9, the location was cleaned of all debris.

18. I hereby certify that the foregoing is true and correct

SIGNED Quinn T. Hester

TITLE Prod. Supt.

DATE 3/15/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 3 26 90

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of well and
location of dry hole marker and
surface restoration is completed.

*See Instructions on Reverse Side