

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ RECEIVED

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

MAY - 3 1978

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

O.C.C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

ARTESIA, OFFICE

660' FNL & 1979.4' FEL (Unit letter B)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner B

9. WELL NO.

24

10. FIELD AND POOL, OR WILDCAT

Fren Seven Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

29-T17S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3696' DF

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug & abandon

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Rigged up on 3/17/76. Installed BOP & POH w/69 jts of 2-3/8" OD EUE tbg. WIH w/7" CIBP, set @ 2010'. Circ hole w/heavy gelled mud. Spotted 10 sx Cl H cmt on top of CIBP. Top of plug @ 1970'. Stretched 7" csg, free point indicated @ 1100'. WIH w/jet cutter on WL to 909'. Cut 7" csg @ 909', pulled & recovered. Spotted 35 sx Cl H cmt across 7" OD csg stub @ 909' (100' plug 850-950'). Spotted 35 sx Cl H cmt across 8-5/8" OD csg shoe & top of salt (100' plug 500-600'). Spotted 10 sx Cl H cmt @ surface, inst regulation dry hole marker, plugged & abandoned eff 3/19/76. Cleaned & levelled location in accordance w/USGS & BLM stipulations. Your office to be notified when location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 3/24/76

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE MAY 2 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side