

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THIS MANNER
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <u>SINCLAIR OIL CORPORATION</u>		8. FARM OR LEASE NAME <u>Turner "B"</u>	
3. ADDRESS OF OPERATOR <u>P. O. Box 1920, Hobbs, New Mexico 88240</u>		9. WELL NO. <u>68</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>660' fr South line and 660' fr East line</u>		10. FIELD AND POOL, OR WILDCAT <u>Grayburg Jackson</u>	
14. PERMIT NO.		12. COUNTY OR PARISH <u>Eddy</u>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3747' GR</u>		13. STATE <u>New Mexico</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) Convert existing well to X WIW

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Present Total Depth 3718'. FBTD 3681'. Presently SI.

PROPOSE TO: Set C.I. bridge plug @ approx. 3600' w/2 sks. cement on top. Perforate 4-1/2"OD csg @ approx. following intervals 3454, 3455, 3456, 3475, 3477, 3480, 3482, 3484, 3487, 3489, 3510, 3512'. Acidize perfs. w/approx. 1000 gals. mud acid. Run 2-3/8"OD tubing w/seating nipple in top of tension packer set @ 3409', hookup for water injection well in Premier perfs. 3454-3512' Russell-Turner Waterflood Area.

RECEIVED

MAR 17 1969

O. C. C.
ARTESIA, OFFICE

RECEIVED
MAR 10 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Superintendent DATE 3-6-69

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side