

FORMATION RECORD—Continued

[illegible]

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If things or bridges were put in to test for water, state kind of material used, position, and results of pumping or testing.

HISTORY OF OIL OR GAS WELL

16-43094-2 U. S. GOVERNMENT PRINTING OFFICE

Spilled 11" hole 11-6-60.
11-8-60 - set 1608' at 8-5/8"OD 1-55 2 1/4" seg at 1608' & cemented w/650 lbs cement.
12-8-60 DST #1 - 1/160-1194 - test open 2 hrs, measured 20' d1g ind. IFF-Lero,
water. IFF 1108, IFF 2500, IFF 2666, IFF 2694.
1-6-61 DST #2 - 1/730-9779 - test open 2 hrs, measured 20' d1g ind. IFF-Lero,
no water. IFF 1108, IFF 2500, IFF 2666, IFF 2694.
1-9-61 Run Electric logs.
1-10-61 DST #3 - Plugged and abandoned.
Set 40 sack cement plug 2/2560-0166
40 sack cement plug 2/1600-1160
40 sack cement plug 1/1425-1525
40 sack cement plug 1/1140-0940
40 sack cement plug 1/2280-3570
40 sack cement plug 1/1875-3570
15 sack cement plug 1/1425-1525
Regulation 1 1/2" water. Plugged and abandoned.
Set 40 sack cement plug 2/2560-0166
40 sack cement plug 2/1600-1160
40 sack cement plug 1/1425-1525
40 sack cement plug 1/1140-0940
40 sack cement plug 1/2280-3570
40 sack cement plug 1/1875-3570
15 sack cement plug 1/1425-1525
Regulation 1 1/2" water. Plugged and abandoned.

[illegible]

1-9-61 Ben Fletcher, Jr.
(Phone 4-4414)

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-14-2010 BY 60322 UCBAW

1-9-61 107 42 - 4730-5775 - 2nd Street 2nd Floor, 1st Floor, 1st Floor

12-8-60 DST #1 - 1/160-1190 - 100% of black sulphur water. LTP 1108, MPP 2500, MRP 2600, MRP 2600.

11-8-60 - sent 1608' at 8-5/8"OD 1-55 21# csg at 1608' & cemented w/650 slcs cement.