

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☐ WIW

2. NAME OF OPERATOR ARCO Oil and Gas Company
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR
P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL & 660' FEL
AT TOP PROD. INTERVAL: as above
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(other)		

5. LEASE
LC-029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME
Turner "B" FEB 09 1983

9. WELL NO.
76 O. C. D.

10. FIELD OR WILDCAT AREA, OFFICE
Grayburg Jackson OGSA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
30-17S-31E

12. COUNTY OR PARISH Eddy 13. STATE New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3656' GR

RECEIVED
(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MAY 10 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RU 4/27/82, installed BOP, POH w/injection assy. Drill and push CIBP 3470' to 3560'. Set cmt retr @ 3345'. Cmdt thru retr w/100 sx Cl C cmt. Pull out of retr & spotted 100' cmt plug on top of retr. Displaced hole w/10# salt gel. Pulled up hole to 1500'. Spot 100' Cl C cmt plug 1500-1400'. Perf'd 4 1/2" csg w/2 holes @ 538'. Set pkr @ 500' & established circ. Set cmt retr @ 498'. Circulated Cl C cmt thru perfs @ 538' to surface. Pulled out of retr, filled 4 1/2" csg from 498' to surface. Removed wellhead, installed regulation dry hole marker, cleaned and levelled location. P&A eff: 4/28/82. Final Report.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. W. Schmidt TITLE Dist. Drlg. Supt. DATE 5/4/82

APPROVED (This space for Federal or State office use)
(Orig. Sgd.) PETER W. CHESTER
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 8 1983
FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

Post ID-2
5-21-82
P+ A