

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.
30-015-05489

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LH-1832

7. Lease Name or Unit Agreement Name
State 'M'

8. Well No.
1

9. Pool name or Wildcat
Grayburg Jackson

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3,736 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMITS
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Me-Tex Oil & Gas, Inc.

3. Address of Operator
P.O. Box 2070, Hobbs, NM 88241

4. Well Location
Unit Letter C : 330 Feet From The North and 2310 Feet From The West Line
Section 32 Township 17S Range 31E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI & RU - P.O.O.H. with rods and pump.
2. Install BOP, R.I.H. & set CIBP @ 3,196', above perfs.
3. Spot 15 sx. cmt. cap C.I.B.P. @ 3,196'
4. Circ. 9.5#/gal. mud.
5. Spot 25 sx. cmt. plug (B. salt) @ 1,650' - 1550' and tag.
6. Spot 25 sx. cmt. plug (T. salt) @ 750' - 650' and tag.
7. Spot 10 ~~ax~~ cmt. surface plug with marker. SPOT 60' of 5 1/2" x 8 5/8" CAS
8. Cut off wellhead and anchors, cover pit and collar, rig down and move out plugging unit, remove all surface equip. and return surface to natural contour.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Burton Veteto TITLE President DATE 7-22-02
TELEPHONE NO. 397-7750

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE AUG 6 2002

CONDITIONS OF APPROVAL, IF ANY: