Submit 3 Copies to Appropriate District Office

DISTRICT II

State of New Mexico Energy,

Form C	-103
Revised	1-1

PLUG AND ABANDONMENT

erais and Natural Resources Department

DISTRIC	ĽI			
P.O. Box	1980.	Hobbs.	NM	88240

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO		
.3/	1-015-05926	
		٠

5. Indicate Type of Lease STATE

6. State Oil & Gas Lease No.

FEE X

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Drawer DD, Artesia, NM 88210

(DO NOT USE TH	SUNDRY NOTICES AND F IS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE TO (FORM C-101) FOR SU	DRILL OR TO DEE! APPLICATION FOR	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL WELL X	GAS WELL	OTHER	ECEIVEL	Len Mayer
2. Name of Operator YATES PETRO	LEUM CORPORATION	j'r	1995	8. Well No.
3. Address of Operat	or th St., Artesia, NM	88210	JUL 20 .	9. Pool name or Wildcat Venasco Draw (YESO, SA)
4. Well Location Unit Letter	D : 990 Feet From	The North	OIL COM.	
Section	28 Township	185	Range 26E ther DF, RKB, RT, GR, etc.)	NMPM Eddy County
		GL 3	421	
11.	Check Appropriat	e Box to Indica	ate Nature of Notice, R	eport, or Other Data
	OTICE OF INTENTION		SUB	SSEQUENT REPORT OF:
DEDECTON REMEDIA	AL WORK PLUG	AND ABANDON	REMEDIAL WORK	ALTERING CASING

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. MIRU WSU. Ensure well is dead. POOH w/rods & pump. NU & test BOP. POOH w/tubing.
- 2. MIRU wire line unit. Set CIBP at 2350' and cap with 35' cement to abandon YESO. Pressure test casing.

OTHER:

- 3. Perforate San Andres 1596' to 1660' (16 holes). Correlate to CRN/CCL log run 8/3/77.
- 4. RIH with tubing & packer. Acidize perfs w/2500 gals 20% NEFe HCI acid & 50% excess ball sealers. POOH with tubing and packer.
- 5. Frac San Andres. Frac Schedule attached.

OTHER: Abandon Yeso/ Re-complete higher to

6. RIH with tubing, pump, and rods. Turn well to production and test on pump.

CHANGE PLANS

I hereby certify that the information above is true and complete to the best of my know	ledge and belief.	
SIGNATURE Tamela Evans	nne Production Clerk	DATE
TYPEOR FRINT NAME Rusty Klein / Pamela Evans		TELEPHONE NO. 505/748-1471
(This space for State Use) ORIGINAL REGION OF THE W. GUM	m.e	AUG 1 8 1995

APPROVED BY