

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

SEP 24 1975

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name Ballard Grayburg San Andres Unit	
8. Farm or Lease Name Tract No. 25	
9. Well No. 2	
10. Field and Pool, or Wildcat Lozo Hills Queen Grayburg San Andres	
12. County Eddy	

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SAN TA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	O. C. C. ARTESIA, OFFICE
2. Name of Operator Anadarko Production Company	
3. Address of Operator P. O. Box 67, Lozo Hills, New Mexico 88255	
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 18S RANGE 29E NMPM.	

15. Elevation (Show whether DF, RT, GR, etc.) 3550' GL
--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER Fracture Treat <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit, pull rods & tubing.
2. Wash out to T. D.
3. Run GR-Neutron and Caliper logs.
4. Fracture treat Grayburg Zones with 80,000 gals gelledwater, 100,000# sand and 1500 gals 15% Reg. Acid.
5. Put well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by
Jerry E. Buckles

SIGNED

TITLE **Area Supervisor**

DATE **Sept. 22, 1975**

APPROVED BY **W. A. Gressett**

TITLE **SUPERVISOR, DISTRICT II**

DATE **SEP 25 1975**

CONDITIONS OF APPROVAL, IF ANY: