

Memo

From

Bill Gressett
Oil & Gas Inspector

To

Result for running this

3-3-61

taking in hole. has been shut in
for some time.

Plan to work being done today
trying to get well with set
of packers. 10-19-61
H.L.