

LOCATE WELL CORRECTLY

LOG OF OIL OR GAS WELL

Company Picher Oil & Gas Company Address Picher, Oklahoma

Lessor or Tract Permit Field Artesia State New Mexico

Well No. 2 Sec. 12 T. 18 R. 27 E. Meridian N. M. P. M. County Eddy

Location 200 ft. {N.} of S. Line and 200 ft. {W.} of E. Line of Section 12 Elevation 3632 36/6
(Derrick floor relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Signed Chas. Markwardt

Date May 1, 1926

Title Superintendent

The summary on this page is for the condition of the well at above date.

Commenced drilling February 22, 19 26 Finished drilling April 6, 19 26

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

No. 1, from 1982 ft. to 1994 ft. No. 4, from _____ to _____
No. 2, from none to _____ No. 5, from _____ to _____
No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from 405 ft. to 408 ft. No. 3, from _____ to _____
No. 2, from none to _____ No. 4, from _____ to _____

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From	To	
<u>10</u>	<u>40#</u>	<u>10</u>		<u>233</u>		<u>all pulled</u>			
<u>8 1/2</u>	<u>32#</u>	<u>10</u>		<u>411</u>					
<u>6 5/8</u>	<u>20#</u>	<u>10</u>		<u>1916</u>	<u>Braden</u>	<u>shoe, with wall packer.</u>			

CASING OR TOOLS LOST OR SIDETRACKED (NONE)

From _____ to _____ Description _____
From _____ to _____ Description _____
From _____ to _____ Description _____

MUDDING AND CEMENTING RECORD (NONE)

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used

PLUGS AND ADAPTERS (NONE)

Heaving plug—Material _____ Length _____ Depth set _____
Adapters—Material _____ Size _____

SHOOTING RECORD

Shot	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
<u>5 1/2</u>	<u>3</u>	<u>Nitro-Glycerine.</u>	<u>60</u>	<u>Apr. 8, 1926</u>	<u>1982-1994</u>	