

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Mojave, NM 88210

NM-015068

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/> 2. NAME OF OPERATOR Marbob Energy Corporation ✓ 3. ADDRESS OF OPERATOR P.O. Drawer 217, Artesia, New Mexico 88210-0217 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2635 FNL 1325 FWL		RECEIVED BY MAR 23 1987 O. C. D. ARTESIA OFFICE		7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME McKee-Wilson 9. WELL NO. 3 10. FIELD AND POOL, OR WILDCAT Turkey Track SR Qn Grbg 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 34-T18S-R29E 12. COUNTY OR PARISH Eddy 13. STATE N.M.	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3415' GR			


16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugged & abandoned as follows: RU, pulled 2 3/8" tbg & Baker packer out of hole; RIH 2 3/8" tbg to 2094'; set 35 sack plug (410' fill), tagged cmt. @ 1719, POOH to 1506', set 35 sack plug; RIH w/wire line, perforated 2 holes @ 1000', set retainer (927', could not pump into perms; perforated @ 300', set retainer @ 250', circulated cmt. inside and out. Set dry hole marker.



I hereby certify that the foregoing is true and correct

SIGNED Cecilia Gray TITLE Production Clerk DATE 3/12/87

(This space for Federal or State office use)

APPROVED Don TITLE DATE 3-26-87

COPIATIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post FD-2
3-27-87
p4A