SUNDRY NOTICES AND REPORTS ON WELLS . (DO NOT USE THIS FORM TOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM TOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM TOR PROPOSALS.)	
OIL GAS WELL OTHER.	7. Unit Agreement Name South Home Unit
Sunray DK Oil Company	8. Farm or Leane Name South Hope Unit
3. Address of Operator P. O. Box 1416, Roswell, New Mexico	9. Well No.
4. Location of Well 1845.69 UNIT LETTER SK, 1980 FEET FROM THE South LINE AND 1845.69 FEET FROM	10. Field and Pool, or Wildcat Hope Strawm Gas
THE West: LINE, SECTION 30 TOWNSHIP 18 RANGE 23 NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4068 DF	i2. County Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	ner Data REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER Semi-Annu	al TA Report X
R E	CEIVED
•	- -
	JUL 1 4 1966
AR	D. C. C. RTEBIA, OFFICE
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
John Hastings TITLE Production Engineer	DATE 7-13-66
CONDITIONS OF APPROVAL, IF ANY:	JUL 1 4 1966