

COPIES RECEIVED		
DISTRIBUTION		
DATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 21 1983

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-5224	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH OR TO USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- WIW - TA P&P		7. Unit Agreement Name	
2. Name of Operator		W.L.H.U. Grb. #4 SD	
Newmont Oil Company ✓		8. Farm or Lease Name	
3. Address of Operator		Tract 27	
P. O. Box 1305, Artesia, New Mexico 88210		9. Well No.	
4. Location of Well		2	
UNIT LETTER L 2310' FEET FROM THE FSL LINE AND 990' FEET FROM		10. Field and Pool, or Wildcat	
THE FWL LINE, SECTION 1 TOWNSHIP 18 RANGE 29 NMPM.		Loco Hills (Q.G.SA)	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3516'		Eddy	

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/9/83...Spotted 50 sks cement, 1 sk paper. WOC. Hole between 441 and 567'. Tagged plug at 2112'. Perf. 4 shots at 1150'. Set pkr 567'. Communication. Pulled pkr. Reset pkr 567'. Squeezed 50 sks cmt. WOC.

5/10/83..Tagged plug at 895'. Perf. at 415', squeezed 50 sks cmt. WOC. Tagged plug at 368'. Spotted 27 sks at 368'. Installed dry hole marker.

Location ready for inspection.

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ernest J. McNagill</u>	TITLE <u>Area Manager</u>	DATE <u>7/20/83</u>
APPROVED BY <u>Randy Brooks</u>	TITLE <u>Geologist</u>	DATE <u>10/7/83</u>
CONDITIONS OF APPROVAL, IF ANY:		

Don't know  
7-27-83  
P&P