

Jennifer A. Salisbury
CABINET SECRETARY

5-28-99

MIRIAH ENERGY CORP.
P.O. BOX 160430
AUSTIN, TEXAS
78716

Reply Re.
mail(Bridger
915 627 6851

RE: 30-015-10186 H-28-18-30
N. BENSON QUEEN UT #7

30-015-10101 F-28-18-30
N. BENSON QUEEN UT #9

30-015-10131 L-28-18-30
N. BENSON QUEEN UT #14

30-015-04564 D-34-18-30
N. BENSON QUEEN UT #35

30-015-10152 H-33-18-30
N. BENSON QUEEN UT #41

ATT: MARIAH ENERGY CORP.,

THE ABOVE LISTED WELLS FAILED A REQUIRED MIT TEST
IN 1995.

WE HAVE NO RECORD OF ANY REPAIR ON WELLS AS REQUESTED
BY RAY SMITH.

PLEASE REPORT YOUR INTENTIONS TO REPAIR THE ABOVE LISTED
WELLS TO ME AND START THE REPAIRS NO LATER THAN 30
DAYS FROM THE DATE OF THIS LETTER.

SINCERELY,

Mike Stubblefield

MIKE STUBBLEFIELD

FIELD REP 2

N.M.O.C.D.