Form 3160-5 (June 1990) DEP. BURI		
ALL	ARTMENT OF THE ATERIORI ST Street	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
BORI	Artesia, NM 88210-2834	5. Lease Designation and Serial No.
SUNDRY N	IOTICES AND REPORTS ON WELLS	NMNM54184
Do not use this form for proposa Use "APPLICA"	als to drill or to deepen or reentry to a different reservoir TION FOR PERMIT-" for such proposals	6. If Indian, Allottee or Tribe Name
S	SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Gas Well Well Well Other WIV 2. Name of Operator	N	8. Well Name and No. Dunn B Federal #29
Melrose Operating Co.		9. API Well No.
3. Address and Telephone No.		30-015-10117
PO Box 5061, Midland, TX 79704		10. Field and Pool, or Exploratory Area
 Location of Well (Footage, Sec., T., R., M., or 1980' FNL 1980' FEL Sec. 11, T18S, R28E, Unit G 	r Survey Description)	Artesia QN-GB-SA 11. County or Parish, State
		Eddy Co., NM
12. CHECK APPROPRIATE	E BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, C	DR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
-	Recompletion	
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form)
directionally drilled, give subsurface location: 5/31/00 - Notify BLM - MIRU - ND wellhead - N 6/1/00 -	s (Clearly state all pertinet details, and give pertinent dates, including estimated date s and measured and true vertical depths for all markders and zones pertinent to this NU BOP - RIH w/40 jts to tbg - Close in well. c cmt on top. Hole would not circ. POH & spot 25 sx @ 700'. POH & I & tag @ 540'. RIH & perf @ 400'. Spot 35 sx, POH. Close in well.	work.)*
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 -	vacuum. Mix 2 sx cedar fiber. Spot 35 sx @ 416'. POH. WOC. RIH t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to plaga the compared as to plaga	25 sx to surf. RD & cut off ରୁ ଜୀ ଲେକ weil boos. ସେମିଲେଣ until
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 - RIH & tag plug @ 260'. Hole loaded. wellhead. Level pit & cellar. Install dry hole marker.	t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to plagak the constant of the start is a second when the second	25 sx to surf. RD & cut off ରୁ ଜୀ ଲେକ weil boos. ସେମିଲେଣ until
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 - RIH & tag plug @ 260'. Hole loaded. wellhead. Level pit & cellar. Install dry hole marker.	t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to plagak the constant of the start is a second when the second	25 sx to surf. RD & cut off ରୁ ଜୀ ଲେକ weil bocs. ସେମିଜଣ until
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 - RIH & tag plug @ 260'. Hole loaded. wellhead. Level pit & cellar. Install dry hole marker.	t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to plaga in a plaga	25 sx to surf. RD & cut off ຊຸ ເຖິງຄອ ພຣຟ been. ເພີດໃຈເປັ ພາຟຟ ເພດເປັດເປັດ
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 - RIH & tag plug @ 260'. Hole loaded. wellhead. Level pit & cellar. Install dry hole marker. 14. I hereby certify that the foregoing is true and Signed Chis space for Federal or State office use) Approved by	t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to plaga in a plaga	25 sx to surf. RD & cut off
Spot 20 sx @ 706'. POH. WOC. RIH 6/2/00 - RIH & tag plug @ 416'. Hole still on v POH. WOC. RIH & tag @ 296'. Spot 6/5/00 - RIH & tag plug @ 260'. Hole loaded. wellhead. Level pit & cellar. Install dry hole marker. 14. I hereby certify that the foregoing is true and Signed (This space for Federal or State office use) Approved by <u>OPIC SGD.</u> DAVI Conditions of approval, if any:	t 35 sx @ 296'. POH. Close in well. Perf @ 260'. Set pkr @ 100'. Press up to 500#. POH. RIH & spot 2 Approved as to place in a standard of the spot 2 Approved as to place in the Regulatory Tech ID R. GLASS Title PETROLEUM ENGINEER or any person knowingly and willfully to make to any department or agency of the Unit	25 sx to surf. RD & cut off 25 sx to surf. RD & cut off 26 she well boom 26 she well boom 26 she well boom 26 she well boom 26 she well boom 27/20/00 Date 07/20/00 Date 12.200