

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-328978(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

MAY - 4 1978

2. NAME OF OPERATOR

TEXACO Inc. ✓

3. ADDRESS OF OPERATOR

P.O. Box 723, Hobbs, New Mexico 88240

O.C.C.
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

660' FIL & 1980' FEL of Section 28, T-18-S, R-30-E, Eddy Co.,
New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

L.R. Manning Fred. #2

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

North Benson Queen Gb.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 28, T-18-S, R-30-E

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3430' (GR)

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up.
2. Set CIBP @ 2600' & dump 35 sx cement on plug.
3. Perforate 4-1/2" csg w/2 JS @ 1505'. Squeeze perforation w/150 sx Class H cement.
4. Perforate 4-1/2" csg w/2 JS @ 530'. Squeeze perforation w/125 sx Class H cement. Cemented to surface.
5. Install Dry Hole Marker & clean up. Well P&A 4-21-77.

RECEIVED

MAY 02 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Asst. Dist. Supt.

DATE

4-28-77

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

MAY 3 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Protected
P&A
5/5/78