

WEST RED LAKE UNIT 026 ✓

I-8-18S-27E

30-015-00821-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/16/2002	MIT Witnessed -	Gerry Guye	Yes	No	5/17/2002	iGEG020745371

Comments on Inspection: Inspection revealed no bradenhead connection was visible. Since the production casing was not cemented to surface it is requested a valve be installed on the 5½ annulus in order to monitor the area behind the production casing. This valve should be plumbed to the surface with a valve above ground to facilitate setting a gauge for monitoring if necessary.

WEST RED LAKE UNIT 015 ✓

H-7-18S-27E

30-015-10174-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/16/2002	MIT Witnessed -	Gerry Guye	Yes	No	5/17/2002	iGEG020745367

Comments on Inspection: Inspection revealed no bradenhead connection was visible. Since the production casing was not cemented to surface it is requested a valve be installed on the 4½ annulus in order to monitor the area behind the production casing. This valve should be plumbed to the surface with a valve above ground to facilitate setting a gauge for monitoring if necessary.

ATOKA SAN ANDRES UNIT 141 ✓

J-13-18S-26E


30-015-10550-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/16/2002	MIT Witnessed -	Gerry Guye	Yes	No	5/17/2002	iGEG020745358


Comments on Inspection: Inspection revealed no bradenhead connection was visible. Since the production casing was not cemented to surface it is requested a valve be installed on the 5½ annulus in order to monitor the area behind the production casing. This valve should be plumbed to the surface with a valve above ground to facilitate setting a gauge for monitoring if necessary.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infra-structure of the oil and gas industry.

Sincerely,



Oil Conservation Division, District II



Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
 *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.