

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-033775

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER**Injection Well**

2. NAME OF OPERATOR

TEXACO Inc. ✓

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface**Unit letter P, 330' FSL, 330' FEL, S-28, T-18-S,
R-30-E**

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3481 DF

9. WELL NO.

23

10. FIELD AND POOL, OR WILDCAT

**North Benson
Queen Grayburg**11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 28, T-18-S, R-30-E**

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☒REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pld tubing & 4 1/2" pkr. Ran 2" tubing & set RBP @ 3347' w/pkr @ 3315'. Acidize perfs. 3332-3345. Pressured zone to 3,000#. Communicated. Reset pkr at 2975'. Acidize perfs 3015-3022, 3332-3345 (upper & lower penrose) w/ 1500 gals. 15% acid w/10% Musol & 5 gals Morfio
2. Flushed w/13 BFW. Pressure 3,000#. Pumped 12 BFW into both zones @ 1/2 BPM @ 1600#. Complete 2:00 P.M. 5-6-75.
3. Rel pkr. POH lost RBP. Ran retr. tool. Recovered BP.
4. Ran 4 1/2" Guiberson UN-I pkr 6 & 90 jts. 2 3/8" PC tubing. Set pkr. @ 2756'. Tested 500# OK. Rel pkr. displaced tbg, sang annulus w/25 gals. Cardinal No-Cor 439 mixed w/ 57 BFW. Reset pkr.
5. Returned well to injection at 730 BWPD @ 1650psi.

RECEIVED

MAY 15 1975

O. C. C.
ARTESIA. OFFICE

RECEIVED

MAY 13 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNATURE

TITLE

Asst. Dist. Supt.

DATE

May 12, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

MAY 14 1975

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment: data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.