Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICTI

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

WELL API NO.		
5. Indicate Type of Lea	STATE	FEE

P.O. Box 1980, Hobbs, NM 88240	P.O. Bo	P.O. Box 2088 Santa Fe, New Mexico 87504-2088				i	
DISTRICT II P.O. Drawer DD, Artesia, NM 88216	Santa Fe. New Me			. Indicate Type of	of Lease		
DISTRICT III	-	JUN 2 <b>4_1991</b>			STATELX	FEE	
1000 Rio Brazos Rd., Azzec, NM 87410  O. C. D.		- 10	6. State Oil & Gas Lease No.				
OLINDOV A	NOTICES AND REPORTS ON				647 ////////////////////////////////////		
( DO NOT USE THIS FORM FOR	NOTICES AND REPORTS ON R PROPOSALS TO DRILL OR TO DE RESERVOIR. USE "APPLICATION FO RM C-101) FOR SUCH PROPOSALS	EPEN OR PLUC OR PERMIT"		. Lease Name or	Unit Agreement Nam	<i>(/////////</i> le	
1. Type of Well:	OTHER			Resler Ya	tes State		
2. Name of Operator	· — — — —			. Well No.			
Arch Petroleum Inc.	<u></u>			317			
3. Address of Operator	420 East Midland To	vac 70705	I -	. Pool name or V U−GB−SA A			
10 Desta Dr., Suite	420 East, Midland, Te	AGS / 3/ U3		O-UD-JA A	1 00314		
	1650 Feet From The North	u	ne and 1650	Feet From	The West	Line	
Section 21	Township 18S	Range 2	8E NM	pm Edd	y	County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3567 GR							
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:							
r	PLUG AND ABANDON	BEMER	IAL WORK	IXI	ALTERING CASING	G $\square$	
PERFORM REMEDIAL WORK L	CHANGE PLANS		ENCE DRILLING O		PLUG AND ABANG		
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB						
OTHER:		OTHER					
12. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent de	tails, and give per	inent dates, including	estimated date of	of starting any propose	d	
5-28-91 Logged 1000	O' of hole. Perforate	d 2074-208	4 with 2 JS	SPF (17 ho	oles).		
5-29-91 Acidized with 1000 gals 15% NeFe HCL acid with 40 ball sealers at 3.3 BPM 1800 psi. ISIP: 1300#. 15 SIP: 970 psi. Open well up. Swab to recover load.							
5-30-91 Frac with 16,000 gals 30# gel water and 36,000# 12-20 sand in 5 stages at 14 BPM 2800 psi. ISIP: 2800#. 15 SIP: 1200#.							
6-01-91 Open well up, flowing back sand. Shut down. Tag frac sand 60' off TD. Circulate hole clean. Ran production string. Put well on pump.							
I hereby certify that the information above	re is true and complete to the best of my knowle		· · · ·			10 01	
SIGNATURE	if Hulle	∠ TITLE	perations N	lanager	DATE6	19-91	
TYPE OR PRINT NAME David M	iller		915-685-1	1961	TELEPHONE NO.	· · · · · ·	
	ORIGINAL SIGNED BY MIKE WILLIAMS				11181: -	a e 1001	
	RAINE WILLIAMS			1	JUNE	2 8 <b>1991</b>	