

| | |
|-----------------|-------------------------------------|
| COPIES RECEIVED | |
| TRIBUTION | |
| FE | <input checked="" type="checkbox"/> |
| | <input checked="" type="checkbox"/> |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | <input checked="" type="checkbox"/> |

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 29 1982

O. C. D.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. B-5524 | |

SUNDRY NOTICES AND REPORTS ON WELLS, ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. <input type="checkbox"/> WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW - TA | 7. Unit Agreement Name WEST LOCO HILLS GRB #4 SD |
| 2. Name of Operator NEWMONT OIL COMPANY | 8. Farm or Lease Name TRACT 30 |
| 3. Address of Operator P. O. BOX 1305, ARTESIA, NEW MEXICO 88210 | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER P 660' FEET FROM THE FSL LINE AND 660' FEET FROM THE FEL LINE, SECTION 11 TOWNSHIP 18S RANGE 29E NMPM. | 10. Field and Pool, or Wildcat LOCO HILLS (O. G. SA) |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3510' | 12. County Eddy |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tubing and packer
2. Spot sufficient cement across producing interval to tie back to production string casing seat, or set bridge plug near casing seat and cap with 25 sack cement plug
3. Perforate base of salt @ 975' and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate top of salt @ 472' and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface tying surface and production casing together.
6. Erect permanent well marker

Note: (A.) Your office will be notified 24 hrs. prior to operations
(B.) All plugs will be verified
(C.) Hole will be loaded between all plugs with 10# mud
(D.) We do not plan to pull any casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|--|------------------------------------|------------------------|
| SIGNED <u>E. J. McHenry</u> | TITLE <u>Area Manager</u> | DATE <u>7/28/82</u> |
| APPROVED BY <u>M. J. Walker</u> | TITLE <u>OIL AND GAS INSPECTOR</u> | DATE <u>AUG 3 1982</u> |
| CONDITIONS OF APPROVAL, IF ANY: * As Noted Above | | |
| Notify N.M.O.C.C. in sufficient time to witness <u>Plugging</u> | | |