

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

MAR 23 1983

O. C. D.

ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-5524
7. Unit Agreement Name West Loco GRB # 4
8. Farm or Lease Name Tract 30
9. Well No. 2
10. Field and Pool, or Wildcat Loco Hills
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>WIWPA</u>
2. Name of Operator Newmont Oil Company
3. Address of Operator P.O. Box 1305 Artesia, New Mexico 88210
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>FSL</u> LINE AND <u>660</u> FEET FROM THE <u>FEL</u> LINE, SECTION <u>11</u> TOWNSHIP <u>18S</u> RANGE <u>29E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3510

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-19-83 Set CIBP @ 2577' and capped with 7 sacks of cement.
- 1-24-83 Spotted 18 sack plug at 1500'. (Block)
- 1-25-83 Squeezed 50 sack plug 1000 psi. tag top @ 855'.
- 1-25-83 Squeezed 98 sack plug. Circulated annulus. Tag top of 4½ @ 170'. (450' of perms)
- 1-26-83 Cut off wellhead. Placed 15 sack surface plug. Installed dry hole marker.

Location ready for inspection

Post FD-2
4-1-83
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ernest J. McLaughlin</u>	TITLE <u>Area Manager</u>	DATE <u>3/22/83</u>
APPROVED BY <u>Harry Brooks</u>	TITLE <u>Geologist</u>	DATE <u>12/7/83</u>
CONDITIONS OF APPROVAL, IF ANY:		