

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

YOUR APPLICANT
Must Submit Form No. 42-10004
5. LEASE TERMINATION AND SERIAL NO.
1C-058480 *ckf*
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☐ GAS ☐ WELL ☐ OTHER ☐ <i>WIW - JA</i> <i>APR 06 1983</i>		7. UNIT AGREEMENT NAME <i>W.L.H.U. GRB #4 SD UT</i>	
2. NAME OF OPERATOR <i>NEWMONT OIL COMPANY</i>		8. FARM OR LEASE NAME <i>TRACT 10B</i>	
3. ADDRESS OF OPERATOR <i>P. O. BOX 1305, ARTESIA, NEW MEXICO</i>		9. WELL NO. <i>6</i>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>66A FNL 660 FEL Sec. 3-18-29</i>		10. FIELD AND POOL, OR WILDCAT <i>LOCO HILLS (Q.G.SA)</i>	
14. PERMIT NO.		15. ELEVATIONS (Show whether DT, RT, GR, etc.) <i>3538' GL</i>	
		12. COUNTY OR PARISH <i>EDDY</i>	
		13. STATE <i>NEW MEXICO</i>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT ☒
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandon as follows:

12/1/82.....Spotted 50 sacks cement plug at 2483'.

12/2/82.....Casing leaked. Tagged bottom plug at 1665'. Perf base of salt at 883' and spotted 25 sacks cement plug at 933'.

12/3/82.....Tagged plug at 853'. Pulled up to 420' and perf top of salt. Ran tbg to 853' and spotted 125 sacks cement.

12/4/82.....Tagged plug @ 853..... Circ. to surface behind 4 1/2".

12/5/82.....Tagged plug at 90'. Pressured up to 500#. Set dry hole marker at surface w/ Location ready for inspection

RECEIVED

MAR 30 1983

OIL & GAS
MINERAL SERVICE
ROOSEVELT, NEW MEXICO

Post ID-2
4-15-83
P+A

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

3/28/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: