

Form 1-391 BY
May 1983

OCT 2 - 1985

O. C. D. SUNDY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NEW MEXICO
ARTESIA, NM 88210

REPLICATE
MISSION

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-058480

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

W.L.H.U. GRB #4 SD UT

8. FARM OR LEASE NAME

TRACT 10B

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

LOCO HILLS (O.G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC ---3-18S-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3538' GL

12. COUNTY OR PARISH
EDDY

18. STATE
NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

XX

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows:

12/1/82.....Spotted 50 sacks cement plug at 2483'.

12/2/82.....Casing leaked. Tagged bottom plug at 1665'. Perf base of salt at 883' and spotted 25 sacks cement plug at 933'.

12/3/82.....Tagged plug at 853'. Pulled up to 420' and perf top of salt. Ran tbg to 853' and spotted 125 sacks cement.

12/4/82.....Tagged plug @ 853..... Circ. to surface behind 4 1/2".

12/5/82.....Tagged plug at 90'. Pressured up to 500#. Set dry hole marker at surface w/ (15 sp plug)
Location ready for inspection

RECEIVED

MAR 30 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

OIL & GAS
MINERALS RIGHT. SERVICE
ROSWELL, NEW MEXICO

DATE

3/28/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

9-30-85

*See Instructions on Reverse Side