	•	the support	englisering for the energy of the section of the control of the section of energy meaning at the con-
STATE OF NEW MEXICO		ent.	•
ENERGY AND MINERALS DEPARTM		•	
DISTRIBUTION	7	ATION DIVISION	
SANTA FE SANTA FE, NEW MEXICO 87501		Form C-103 Revised 10-1-78	
FILE	-	W MEXICO 87501	5a. Indicate Type of Lease
U.S.G.S.	-	DEC 08 '87	State Fee
OPERATOR	<u>.</u>	DEC 00 07	5. State Oil & Gas Lease No.
		O, C, D	B-4109
SUNDI PA MOT MAROT CINT BEU TON OD! SUNDAMA" BEU	RY NOTICES AND REPORTS OF PLUG	N WELLS	
1.	TION FOR PERMIT = " (FORM C-101) FOR 3	UCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
J. Pete Thom J. Address of Operator	pson		9. Well No. jamar State
403 2nd Plac	e, Abernathy, Texas	70311	3. 1101.
4. Location of Well	·		10. Field and Pool, or Wildcat
UNIT LETTER	980 PEET PROM THE East	LINE AND 330 PEET PR	om Maljamar State
North	10N 36 TOWNSHIP 17 5	21 5	
THE LINE, SECT	TOWNSHIP 1/9	MANGE 31 E	·· (
	15. Elevation (Show wheth	er DF, RT, GR, etc.)	12. County
		3842 Gr	Eddy
Check	Appropriate Box To Indicate	Nature of Notice, Report or (
NOTICE OF I	NTENTION TO:	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON Y	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABAHDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
OTHER		OTHER	
17 Departs Departs of Completed			
work) SEE RULE 1103.	operations (Crearry state all perfinent d	etails, and give pertinent dates, includ	ing estimated date of starting any proposed
		÷	
(1) Set CIBP @	3900' <u>+</u> W/35'cmt. Cap	0	•
		•	
(2) Load hole	w/mud		
(3) Find TOC b	ehind 4½" casing		
	ll csg @ +		
		•	
(5) Spot 35 Sx	·cmt inside & outside	e stub & tag	
(6) Spot 25 S _X	@ 3240' - Top Queen	- 3192'	
(7) Spot 25 Sx	@ 2170' - Base Salt	TX990' BX2120	
(8) Spot 35 Sx		0 5.40	
	@ 1100 & tag - Sh	noe 8: 5/8	

CONDITIONS OF APPROVAL OF ANY

OIL AND GAS INSPECTOR

OWNER

DATE DEG 10 7987