

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE

NM-27280

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Light A

9. WELL NO.

1-4

10. FIELD OR WILDCAT NAME

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29, T-18-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

1. oil well ☐ gas well ☐ other Re-Plug Well

2. NAME OF OPERATOR

TEXACO Inc. Wolfson Oil Co

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1370' 130/W

AT TOP PROD. INTERVAL: Unit Letter 'L'

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☐

(other) To: Re-Plug Well

SUBSEQUENT REPORT OF:

RECEIVED

AUG 18 1979

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TEXACO Inc. proposes to re-enter &amp; re-plug subject P &amp; A well formerly operated by Wolfson Oil Co. This operation is to comply with letter from NMOCD, 4-30-79, informing TEXACO of surface leaks on wells off-setting TEXACO'S North Benson Queen Unit.

1. Rig up. Remove Dry Hole Marker. Install BOP.

2. Drill out cement plugs to 3080' (TD).

3. Spot 90 sx. cement plug from 3080' - 2500'.

4. Spot 30 sx. cement plug from 1800' - 1600'.

5. Spot 35 sx. Cement plug from 600' - 400'.

6. Spot 10<sup>2</sup> sx. Cement plug from 50' - surface.

7. Install Dry Hole Marker, Clean up location.

RECEIVED

JUN 2 1980

O. C. D.  
ARTESIA, OFFICE

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Asst. Dist. Supt.

DATE

8-9-79

(Or, Self) GEORGE H. STEWART

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 30 1980