

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN **PLICATE***
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO. **NH 025530**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER 2. NAME OF OPERATOR The Atlantic Refining Company 3. ADDRESS OF OPERATOR P. O. Box 1972, Roswell, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2086' FLL, 140' FLL 14. PERMIT NO.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Rondo Federal "B" 9. WELL NO. 1 10. FIELD AND POOL, OR WILDCAT Red Lake SA 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4, T-18N, R-27E 12. COUNTY OR PARISH Adair 13. STATE K. N.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3565' DF	

**RECEIVED
DEC 24 1964
O. C. C.
ARTESIA, OFFICE**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was drilled, cased and cemented by William Paison in October, 1963, but was not completed. We now propose to complete in the San Andres zone as follows:

1. perforate w/2 jets/foot at 2193, 2194, 2195, 2196 & 2207.
2. treat w/1000 gallons 15% acid, 10,000 gallons slick water containing 15,000 lb. 20/40 sand.
3. perforate w/1 jet shot at 2021, 2022, 2023, 2107, 2116, 2124, 2132, 2139, 2147, 2173 and 2174.
4. treat these perforations w/1000 gallons 15% acid and 10,000 gallons slick water. 15,000 lb. 20/40 sand.
5. run 2" tubing for completion and place well on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Drilling Supervisor

DATE

12-15-64

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED
DEC 16 1964
H. L. SULLIVAN
ACTING DISTRICT ENGINEER**

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

