

Address

Midland, Toron

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved.	W.
Land Office	$-\frac{1}{2}$
: ₾ 6 62 0 23	

r orm r	pprovodi	·
Land Office		
Lease No.	LC 062029	
** **	N	

1
-

(IND)CATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Warch 5	, 19 <u></u>
Well No. 1-W is located.	$\frac{5}{S}$ ft. from $\begin{bmatrix} N \\ S \end{bmatrix}$ line and	ft. from $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$ line of sec.	34
SE 1/4 of SVI 1/4	18-5 27-8	NMP	
(% Sec. and Sec. No.) Turksy Track	(Twp.) (Range)	(Meridian)	
(Field)	(County or Subdivision)	(State or Territory)	
The elevation of the derrick floo	or above sea level is 3423 f	ft. (location 3' lower than s	urvey)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

-4 % - 20 6	In lieu of 8 5/9" - 24# surface casing we plan to set approximately 380" surface casing.
34 / - 44°	KECEIVED CEIVED
	In lieu of 8 5/5" - 24" surface casing we plan to set approximately see surface casing. MARS 1961 MARS 1961
I understar	od that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.
Company	306 Wikinson-Foster Building

By Wen. E. Fickert

Title Agent

