

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501RECEIVED  
JUN 27 1984  
O. C. D.  
ARTESIA, OFFICEForm C-103  
Revised 10-1-

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9292


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name North Benson Queen Unit
Name of Operator TEXACO Inc.	8. Farm or Lease Name North Benson Queen Unit
Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 32
Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 18-S RANGE 30-E. NMPM.	10. Field and Pool, or Wildcat Benson Queen Grayburg No
15. Elevation (Show whether DF, RT, GR, etc.) 3436' (DF)	12. County Eddy

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Additional Perforations <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
2. CLEAN OUT.
3. PERFORATE 4 1/2" CASING W/2-JSPF @ 2576', 2590'-2630', 2681', 2703', 77', 2805', 09', 26', 2924', 28', & 2932'.
4. SET PKR @ 2725'. ACIDIZE PERFS AND OPEN-HOLE 2575'-3151' W/4000 GALS 15% NEFE ACID USING 500# ROCK SALT BETWEEN STAGES.
5. RETRIEVE PKR AND BOP. INSTALL PRODUCTION EQUIPMENT. TEST AND PLACE ON PRODUCTION.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Asst Dist Mgr	DATE 6-25-84
APPROVED BY _____	Original Signed By TITLE Leslie A. Clements Supervisor District II	DATE JUN 28 1984

CONDITIONS OF APPROVAL, IF ANY:

...the ...