

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 5 '90

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name RESLER YATES STATE
8. Well No. 341
9. Pool name or Wildcat ON, GB, SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3546 GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	
2. Name of Operator Arch Petroleum Inc.	
3. Address of Operator 777 Taylor St. II-A Fort Worth, Texas 76102	
4. Well Location Unit Letter N : 990 Feet From The South Line and 1650 Feet From The West Line Section 29 Township 18 Range 28 NMPM EDDY County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Convert to Producer <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-20-90 MIRU workover unit to repair hole in tubing. Unseated packer; packer was stuck at 1879' Parted tubing at 1054'. Ran overshot and recovered 10' of tubing. Ran overshot and Hyd. jars. Jarred on packer til dark.

2-21-90 Ran series of overshots. Jarred on packer. Did not recover packer.

2-22-90 Ran overshot and series of Jars. Did not recover packer.

2-23-90 Ran string shot to 1786'-backed off tubing. Three JTS tubing on top of packer. Ran overshot and jarred on packer. Did not recover packer.

2-26-90 Laid down workstring ran in hole with 1759' 2 3/8" tubing, ran pump and rods. convert to Producer. Hook up flowline.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim B. Paschall TITLE V.P. Operations DATE 2/27/90

TYPE OR PRINT NAME Jim B. Paschall TELEPHONE NO. 817-332-9209

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE MAR 6 1990

CONDITIONS OF APPROVAL, IF ANY: