•	X				CIST	
Form 3169-5 (August 1999)	UNITED STATES DEPARTMENT OF THE INTE	RIOR	Cons. Divis	FORM APPROVED OMB No. 1004-0135 Expires November 30, 20		
	BUREAU OF LAND MANAGEM	ENT N M OI	Cons. Dim	5. Lease Serial No.	······	
SUNDE	RY NOTICES AND REPORTS	ON WELLS	at Street	LC-056014		
abandoned w	BUREAU OF LAND MANAGEM RY NOTICES AND REPORTS his form for proposals to drill rell. Use Form 3160-3 (APD) for RIPLICATE - Other instruction	such proposals	NM 88210-20	If Indian, Allottee or Tribe Na	ime	
SUBMIT IN TF	RIPLICATE - Other instructio	ns on reverse :	side 72	7. If Unit or CA/Agreement, Nar	me and/or No.	
1. Type of Well			* 1.15			
Oil Well Gas Well Other Name of Operator				8. Well Name and No. WLHU G4S Unit Tract 8A-3		
Yates Petroleum Corporation OCD ¹² UE/VFD				9. API Well No.		
3a. Address 3b. Phone No. (include area code)				30-015-20035		
105 S. 4th St Artesia, NM 88210 505-748-1471				10. Field and Pool, or Exploratory Area		
 Location of Well (Footage, Sec., T., R., M., or Survey Description) 2600' FNL & 1200' FWL of Section 10-T18S-R29E (Unit E, SWNW) 				Loco Hills-Q-GB-SA 11. County or Parish, State	<u>i</u>	
2000 FNL & 1200	FWL of Section 10-T18	S-R29E (Unit	E, SWNW)	The county of Parish, blace		
				Eddy Co., NM	1	
12. CHECK AI	PROPRIATE BOX(ES) TO INC	DICATE NATUR	E OF NOTICE, RE	EPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION				<u> </u>		
. <u></u>		Deepen	Production (Start/)	(Resume) 🔲 Water Shut-Off		
X Notice of Intent		Fracture Treat	Reclamation	Well Integrity		
Subsequent Report		lew Construction	Recomplete	Other		
	🗋 Change Plans 🛛 🖾 P	lug and Abandon	Temporarily Abai	ndon		
Final Abandonment Notice	Convert to Injection	lug Back	Water Disposal			
Attach the Bond under which the following completion of the invites the sting has been completed. Fi determined that the site is ready Propose to plug at 1. Set CIBP at 2. Spot a 40 sack Cla 2. Perforate 4-1, 3. TIH with wire tubing and sting Class C cement. If 4. TIH with wire tubing. Sting in cement with 2% Cac TOOH with tubing. casing with 4 hole	nd abandon as follows: 516'. TIH with tubing ass C cement plug from /2" casing with 4 holes line set cement retaine into retainer. Establi Leave 35' of cement on line set cement retaine to retainer. Establish C12 from near the surfa If circulation was no es at 277'. Tie onto 4	and tag CIB and tag CIB 2516-1937'. at 1010' a at 1010' a ar and set r top of reta ar and set r circulation to circulation to to 432'.	P. Load hole tion or recompletion in ments, including reclan TOOH with t nd 4 holes at etainer at 91 tion rate. S iner. TOOH w etainer at 33 n. Squeeze w Leave 35' o ed during thi. g and establi.	ed subsequent reports shall be filed n a new interval, a Form 3160-4 sha nation, have been completed, and t ubing. 432'. 0'. TOOH. TIH wit queeze with 50 sack with tubing. 2'. TOOH. TIH wit tith 60 sacks Class f cement on top of s stage, perforate sh circulation. At	I within 30 days all be filed once the operator has the operator has the operator has the operator has the operator has the operator has the operator has the operator has the operator has the o	
14. I hereby certify that the foregoin	nt to surface with an a		CONTINUED ON		% CaCl2.	
Name (Printed/Typed)		Title O.				
Rusty Klein			perations Tec	hnician		
Signature Kusty	Hein		une 17, 2001	APPROVE	:D	
<u> </u>	V THIS SPACE FOR FI	EDERAL OR STA	TE OFFICE USE			
	TACHED FOR	Title		Date UL 3 0 2001		
Conditions of a provide the subject lease of the su			GARY GOURLEY			
Title 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraudule	tle 43 U.S.C. Section 1212, make it a crit ent statements or representations as to any	ne for any person kno matter within its juris	owingly and willfully to sdiction.	> make to any department or agency	of the United	



•

. i a .

1

YATES PETROLEUM CORPORATION WLHU G4S Unit Tract 8A-3 Section 10-T18S-R29E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

Spot a 15 sack Class C cement plug at surface.
 Install regulation abandonment marker.

NOTIFY BLM-CARLSBAD (505-234-5909) AND OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

Rusty Klean

Operations Technician June 17, 2001





....

7

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within thirty (30) days from the approval date of this Notice of Intent to Abandon.

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 505-627-0272, Eddy County call 505-234-5972; for wells in Lea County call 505-393-3612. 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

(rev. 5/30/2000)

acs -- coa.p&a